

## Service Bulletin

Bulletin No. 06-06  
July 28, 2006

**To:** ITW Ransburg and ITW Automotive Finishing Distributors  
**Subject:** Obsolescence of Catalyst Flow Sensor Module

The catalyst flow sensor module (P/N 22-1046), used in the RCS and RCS-2 units, has been obsoleted. We have identified alternate unit to be used as a replacement (P/N A11739-00). Refer to the drawings below to replace a 22-1046 with a A11739-00

