

---

## SERVICE INSTRUCTION

---

**DISPOSABLE EQUIPMENT COVERS FOR:** AER500, EMF-502, EMF-504, EMFD-500, EMFD-502, EMFD-504, 75957, 76690, 70929, 73164, 70404, 72074, 75980, 75785, 75979, 75786, 75982, 72364, 75981, 75760, 19372, 70393, 75787, 75795, 75850, 76478, 76505, 72275, 73499

The following disposable equipment covers are not intended to be laundered. As the name implies, they are disposable and should not be cleaned or laundered and reused. Covers can absorb the cleaning material into the seams, creating a conductive path for high voltage. This can overstress the dielectric properties of the components of the electrostatic atomizer causing it to fail.

**Disposable Equipment Covers P/N: LSMM0029, LSMM0030, GC-100, 72558, 75777, 76116, 76738, 76637, A10772-50, A10772-10, A10772-01, A11565-00, A11564-00**

When the covers are washed in solutions containing polar solvents or water based solutions, a conductive residue can remain on the surface that will affect the performance and safety of the atomizer.

Due to the variables of each installation, the frequency of changing equipment covers may be as often as each shift or as long as once per week.

### Manufacturing

1910 North Wayne Street  
Angola, Indiana 46703-9100  
Telephone: 260/665-8800  
Fax: 260/665-8516

### Technical/Service Assistance

Automotive Assembly and Tier I  
Industrial Systems  
Ransburg Guns  
www.itwransburg.com

Telephone: 800/ 626-3565 Fax: 419/ 470-2040  
Telephone: 800/ 233-3366 Fax: 419/ 470-2071  
Telephone: 800/ 233-3366 Fax: 419/ 470-2071

**Technical Support Representative will direct you to the appropriate telephone number for ordering Spare Parts.**

© 2007 Illinois Tool Works Inc. All rights reserved.  
Models and specifications subject to change without notice.



Form No. SI-07-04  
Litho in U.S.A.  
05/07