
CCV-402-SS & CCV-403-SS

1. When installing the 1/4" pipe plug, 1/4" material inlet fitting, or the 1/8" inlet fitting body, use a good quality pipe sealant or Teflon tape.
2. When installing the valve assembly into any of the optional adapters or manifold blocks, DO NOT use pipe sealant or Teflon tape. DO NOT overtighten the spanner nut (132-156 lbs•in max.).
3. CCV valve must be supported while tightening the tube fittings to prevent damage to the valve seats, or remove the valve before tightening the fluid inlet fittings.
4. Circulation system lines must have a flexible connection between the "hard piping" and the valve.

Refer to current Service Manual for complete information.