


SERVICE INSTRUCTION

79871-00 and 79871-01 Coiled Fluid Tube Assembly for Vector Solo 79900



79871-00 & 79871-01 COILED FLUID TUBE ASSEMBLY			
Item#	Part #	Description	Qty
1	79879-00	Coiled Fluid Tube, 16 Coils (for 79871-00 assembly)	1
	79879-01	Coiled Fluid Tube, 12 Coils (for 79871-01 assembly)	
2	79864-00	Insert, Coiled Fluid Tube	2
3	EMF-202-04	Ferrule, Back 1/4" Tube	2
4	EMF-203-04	Ferrule, Front 1/4" Tube	2
5	79385-01	Nut, Connector Hose	2
6	79890-00	Coiled Fluid Tube Cover	1

Manufacturing

1910 North Wayne Street
Angola, Indiana 46703-9100
Telephone: 260/665-8800
Fax: 260/665-8516
www.itwransburg.com

Technical/Service Assistance

Telephone: 800/ 626-3565 Fax: 419/ 470-2040
Telephone: 800/ 233-3366 Fax: 419/ 470-2071

Technical Support Representative will direct you to the appropriate telephone number for ordering Spare Parts.

